

MA-3/5 Spectrophotometer

TOP-Spectrophotometer



User Guide





Compliance Information

To view E label Compliance information for WiFi devices, choose **Settings > Device Information > Device Label**

CE Declaration



Hereby, X-Rite, Incorporated, declares that this model is in compliance with the essential requirements and other relevant provisions of Directive(s) EMC Directive 2014/30/EU, LVD 2014/35/EU and RoHS EU 2015/863.

Models with WiFi:

CE Mark: Radio Equipment Directive (2014/53/EU) CE 1177

EN 300 328 V2.1.1

EMC : EN 301 489-1 V2.1.1, EN 301 489-17 V.3.1.1,

EN 55022:2010/AC:2011, EN 55024:2010

Health : EN 62311: 2008

Safety : EN 60950-1:2006+A11:2009+A1:2010+A12:2011+A2:2013

Federal Communications Commission Notice

NOTE: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at his own expense.

Models with WiFi:

FCC ID: LSV-TOPAZ

NOTICE:

Changes or modifications made to this equipment not expressly approved by X-Rite, Incorporated may void the FCC authorization to operate this equipment.

Industry Canada Compliance Statement

CAN ICES-3 (A) / NMB-3 (A)

Models with WiFi:

IC ID: 20894-TOPAZ

NOTICE:

Changes or modifications made to this equipment not expressly approved by X-Rite, Incorporated may void the FCC authorization to operate this equipment.

Modèles avec Wi-Fi :

IC ID : 20894-TOPAZ

REMARQUE :

Les changements ou modifications apportés à cet équipement sans l'autorisation expresse de X-Rite, Incorporated peuvent annuler l'autorisation d'utilisation de cet équipement accordée par la FCC.

Japanese Ministry of Internal Affairs and Communications (MIC)



R 201-150256

SRRC (State Radio Regulation of China) Certification

CMIIT ID: 2018DJ1800

TOP-Spectrophotometer



Brazil



10993-20-13091

Modelo: TOP-Spectrophotometer

Para maiores informações, consulte o site da ANATEL www.anatel.gov.br

Este equipamento não tem direito à proteção contra interferência prejudicial e não pode causar interferência em sistemas devidamente autorizados.

Mexico



IFT: RCPXRTO20-1443

Belarus



Argentina

CNC ID: C-25204

South Africa



TA-2020/5655

India

ETA - SD - 20200301921

Russia



Korean Battery Application

Korean battery safety standard KC 62133(2015-07), Application No. XU101195-18004A

Equipment Information

Use of this equipment in a manner other than that specified by X-Rite, Incorporated may compromise design integrity and become unsafe.

To avoid discomfort, do not look directly into the measurement optics when the instrument is on.

No user serviceable parts in this product.

WARNING: This instrument is not for use in explosive environments.

Do not immerse the instrument in liquid.

Transportation: This product contains a lithium-ion battery. Should you need to ship this device, you may wish to consult published guidance documents by one or more of these organizations for advice on how to comply with the regulations: IATA, ICAO, IMDG & PHMSA. The battery contained in this device is 46g in weight, 3.6V, 2.15 Ah, and complies with the UN 38.3 tests in effect the year it was originally shipped.

The instrument is a sensitive measurement instrument. If the instrument experiences a drop, a calibration should be performed followed by a self test before any measurements are taken to ensure the instrument is working properly. Refer to the Calibration section for information on performing a Calibration.



Instructions for disposal: Please dispose of Waste Electrical and Electronic Equipment (WEEE) at designated collection points for the recycling of such equipment.

Firmware Software Licenses

1. Firmware consists of source code of:
Copyright 2006, Atmel Corporation
All rights reserved

Redistribution and use in source and binary forms, with or without modification, are permitted provided that the following conditions are met:

- Redistributions of source code must retain the above copyright notice, this list of conditions and the disclaimer below.

- Redistributions in binary form must reproduce the above copyright notice, this list of conditions and the disclaimer below in the documentation and/or other materials provided with the distribution.

Atmel's name may not be used to endorse or promote products derived from this software without specific prior written permission.

DISCLAIMER: THIS SOFTWARE IS PROVIDED BY ATMEL "AS IS" AND ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT ARE DISCLAIMED. IN NO EVENT SHALL ATMEL BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES (INCLUDING, BUT NOT LIMITED TO, PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY OUT OF THE USE OF THIS SOFTWARE, EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.

2. Acknowledgement:
Independent JPEG Group License
The Firmware uses source code under the IJG license

Proprietary Notice

The information contained in this manual is copyrighted information proprietary to X-Rite, Incorporated.

Publication of this information does not imply any rights to reproduce or use it for purposes other than installing, operating, or maintaining this instrument described herein. No part of this manual may be reproduced, transcribed or translated into any language or computer language in any form or by any means: electronic, magnetic, mechanical, optical, manual, or otherwise; without the prior written permission of an authorized officer of X-Rite, Incorporated.

Patents: www.xrite.com/ip

“© 2020, X-Rite, Incorporated. All rights reserved”

X-Rite® is a registered trademark of X-Rite, Incorporated. All other logos, brand names, and product names mentioned are the properties of their respective holders.

Warranty Information

X-Rite warrants this Product against defects in material and workmanship for a period of twelve (12) months from the date of shipment from X-Rite’s facility, unless mandatory law provides for longer periods. During such time, X-Rite will either replace or repair at its discretion defective parts free of charge.

X-Rite’s warranties herein do not cover failure of warranted goods resulting from: (i) damage after shipment, accident, abuse, misuse, neglect, alteration or any other use not in accordance with X-Rite’s recommendations, accompanying documentation, published specifications, and standard industry practice; (ii) using the device in an operating environment outside the recommended specifications or failure to follow the maintenance procedures in X-Rite’s accompanying documentation or published specifications; (iii) repair or service by anyone other than X-Rite or its authorized representatives; (iv) the failure of the warranted goods caused by use of any parts or consumables not manufactured, distributed, or approved by X-Rite; (v) any attachments or modifications to the warranted goods that are not manufactured, distributed or approved by X-Rite. Consumable parts and Product cleaning are also not covered by the warranty.

X-Rite’s sole and exclusive obligation for breach of the above warranties shall be the repair or replacement of any part, without charge, which within the warranty period is proven to X-Rite’s reasonable satisfaction to have been defective. Repairs or replacement by X-Rite shall not revive an otherwise expired warranty, nor shall the same extend the duration of a warranty.

Customer shall be responsible for packaging and shipping the defective product to the service center designated by X-Rite. X-Rite shall pay for the return of the product to Customer if the shipment is to a location within the region in which the X-Rite service center is located. Customer shall be responsible for paying all shipping charges, duties, taxes, and any other charges for products returned to any other locations. Proof of purchase in the form of a bill of sale or receipted invoice which is evidence that the unit is within the Warranty period must be presented to obtain warranty service. Do not try to dismantle the Product. Unauthorized dismantling of the equipment will void all warranty claims. Contact the X-Rite Support or the nearest X-Rite Service Center, if you believe that the unit does not work anymore or does not work correctly.

THESE WARRANTIES ARE GIVEN SOLELY TO BUYER AND ARE IN LIEU OF ALL OTHER WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING BUT NOT LIMITED TO THE IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR APPLICATION, AND NON-INFRINGEMENT. NO EMPLOYEE OR AGENT OF X-RITE, OTHER THAN AN OFFICER OF X-RITE, IS AUTHORIZED TO MAKE ANY WARRANTY IN ADDITION TO THE FOREGOING.

IN NO EVENT WILL X-RITE BE LIABLE FOR ANY OF BUYER’S MANUFACTURING COSTS, OVERHEAD, LOST PROFITS, GOODWILL, OTHER EXPENSES OR ANY INDIRECT, SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES BASED UPON BREACH OF ANY WARRANTY, BREACH OF CONTRACT, NEGLIGENCE, STRICT TORT, OR ANY OTHER LEGAL THEORY. IN ANY EVENT OF LIABILITY, X-RITE’S MAXIMUM LIABILITY HEREUNDER WILL NOT EXCEED THE PRICE OF THE GOODS OR SERVICES FURNISHED BY X-RITE GIVING RISE TO THE CLAIM.

Table of Contents

Introduction and Setup	8
Packaging	8
Powering On	8
Charging the Battery	9
User Interface	10
Navigating the Screen	10
Scrolling through Settings and Jobs	10
Measure Button	10
Contact Sensors, Indicators and LEDs	11
Home Screen	12
Job List Mode	12
Settings Mode	12
WiFi Info/Connect	12
Header Bar	12
Settings Mode	13
Entering Settings Mode	13
Calibration	13
Self Test	13
Measurement Option	14
Dark Mode Option	14
Speaker Option	14
WiFi Option	14
Language	15
N (measurement number) Option	15
Device Information	15
Power Off	15
Date and Time Option	15
Set LCD Color Option	16
Factory Reset Option	16
WiFi Mode	17
Calibration Mode	18
Calibration Reference	18
Calibrating the Instrument	18
Job List Mode	20
Measuring	20
Deleting Jobs	21

Appendices	23
Service Information	23
Cleaning the Instrument	23
Cleaning the Calibration Reference	23
Replacing the Battery Pack	23
Troubleshooting	25
Instrument Specifications	27

INTRODUCTION AND SETUP

The multi-angle spectrophotometer is designed for consistent, precise color measurement of metallic, pearlescent, and other complex special effect finishes.

This manual covers the installation, operation and maintenance of the instrument. Specific instructions for using the instrument with your software application can be found in the software documentation.

Key features of the instrument are:

- Color display with touch screen operation
- Power on/off and measure button
- Three contact sensors located on the bottom of the instrument to aid in proper positioning



Packaging

Your instrument packaging should contain all the items listed below. If any of these items are missing or damaged, contact X-Rite or your Authorized Representative.

- | | |
|-------------------------|----------------------|
| • MA-3/5 instrument | • Screen protector |
| • USB interface cabling | • Spare light seal |
| • Calibration reference | • Soft carrying case |
| • Safety strap | • Stylus |

Powering On


The power/measure button is used to initiate the instrument from a power off state. Simply press the button (1) for about one second to turn on the instrument. If the instrument does not power up after pressing the power button, the battery may require charging. Refer to Charging the Battery section. The instrument is also powered on by plugging the USB cable into your computer's USB port.

Powering Off

The instrument turns off automatically after two hours of nonuse. It is not required to turn off the instrument manually.



When first powered up, the instrument goes through a startup procedure and displays a splash screen before the Home screen appears.



Charging the Battery

General

The battery for your new instrument comes in a low to medium charge state and should be charged before use. Connect the USB cable to the instrument and your computer’s USB port.

Make sure that the USB cable is connected directly to the computer. A connection to a USB port of a keyboard or PC monitor or a bus-powered USB hub is not recommended. PC monitor or keyboard USB ports are low power USB ports.

NOTE: If a powered USB hub is used, make sure the power supply is rated for no more than 5V.



During charging, the instrument switches on and indicates charging with a “lightning bolt” in the battery icon. The instrument will not power off while plugged into the computer USB port, however, it will go into standby mode. This is indicated by a blue pulsing LED.

A full charge from empty will take 6 hours connected to a computer USB port. Alternatively a standard USB charger can be used.

The charging time will not be reduced with a standard USB charger.

A USB charger with at least 500 mA is required. A standard charger with 1 A will not charge any faster.

Battery Icon Information



This icon at the top of the screen would indicate the battery is fully charged.



This icon at the top of the screen would indicate the battery has a sufficient charge for a substantial number of measurements.



This icon at the top of the screen would indicate the battery pack is low, but measurements are still possible. Battery should be charged soon.



The “lightning bolt” in the center of the icon at the top of the screen indicates the battery is charging.

Battery status is also reported in the Device Information menu item of the Settings window.

USER INTERFACE


Navigating the Screen

The instrument features a graphical touch screen display. All functionality is accessed directly through the screen.

Scrolling through Settings and Jobs

The Up (▲) and Down (▼) arrows appears on screens when some settings or jobs cannot be accessed from the main view. You can also swipe the screen up or down to view the additional settings and jobs.

The Left (◀) arrow at the bottom of the screen is used to return the screen to the previous view.




Settings and jobs are accessed by tapping the corresponding icon on the Home screen. For this example, the Settings icon was tapped to open the Settings screen.



Measure Button

The measure button (1) is located on the side of the instrument. This is the same button that is used to power on and off the instrument. You can also tap the screen (2) to initiate a measurement.

NOTE: In case of a firmware crash, this button acts as a RESET button. Remove the USB cable, press and hold the button for 10 seconds and then release. The instrument will turn off. Refer to the Troubleshooting section for additional information.




Contact Sensors, Indicators and LEDs

To aid in proper positioning and ensure repeatability of sample measurements, the instrument incorporates three contact sensors that are arranged around the measurement port. These sensors require an even amount of contact to be applied across all three sensors before a measurement is triggered.

Three contact sensor indicators that appear in the screen as well as the indicator LEDs on the top of the instrument provide positioning feedback. The indicators in the screen are arranged in the same pattern (top, and back) as the contact sensors located around the measurement port.

- **Green Indicator:** ideal contact is being applied to the corresponding sensor. A measurement can be taken when all three indicators illuminate green. If the required contact is not maintained for the duration of the measurement, an error message will appear on the display and the measurement must be retaken.
- **Red Indicator:** the required contact is not being applied to the corresponding sensor. Correct contact must be applied to achieve a green indicator condition.



The multi-color LED located on the front of instrument provides visual feedback on the status of a measurement and contact sensor.

- **Green LED:** Indicates all three contact sensors are activated properly and a measurement can now be triggered.
- **Red LED:** Indicates one or more of the contact sensors is not properly activated or an error has occurred during a measurement.
- **Blue Pulsing LED:** Indicates the instrument is in standby mode with the USB cable plugged into the computer and charging.
- **Green Pulsing LED in standby** (screen turned off): Indicates device is being connected to the WiFi Network.
- **Off:** Indicates the instrument is off and not ready to measure.

Home Screen

When the instrument is powered-up, the home (top level) screen appears after the startup procedure is complete. Select the modes by tapping the icons located on the display screen.



Job List Mode

This mode is the main mode of operation. Jobs are added, selected, deleted, and measurements are taken in this mode. Refer to the Operation section for information.

Settings Mode

The settings mode is used to set and edit the instruments configuration options, and to enter the calibration mode. The settings options should be reviewed before you use your instrument for the first time. Refer to the Settings Mode section for information.

WiFi Info/Connect

The WiFi information screen displays for connection state and IP address.

If the WiFi is set to ON and a network is correctly configured in the settings menu, the device will always be connected to WLAN as soon as available. This is indicated by the WiFi icon in the header bar which turns from greyed-out to white.

If the WiFi is set to OFF in the settings menu, tapping this icon will connect the device once. The connection is terminated after exiting the WiFi Info/Connect screen.

Header Bar

Displays the current mode, time, software connection status (green when connected), WiFi connection (where applicable), and battery charge status.

SETTINGS MODE

Settings mode is used to adjust and view the instrument’s settings. You should review the current settings before using the instrument for the first time. However, you can go back and change these settings at any time.

Entering Settings Mode

1. From the Home screen, tap the **Settings** icon to access the Setting screen.



2. Tap the Settings option you want to edit or activate. Down (▼) and Up (▲) arrow icons appear on the screen when some settings cannot be accessed from the main view. Tap the arrow icons to view the additional settings.



3. Tap the option required.
4. When finished with the options, tap the Left (◀) arrow at the bottom to return the screen to the Home view.
5. Refer below for information on configuring each Settings option.

Calibration



This option is used to activate the calibration procedure.

To access, tap **Calibration**. Refer to the Calibration mode section later in this manual for detailed information on performing a calibration. After a successfully calibration procedure, you are prompted to execute a self test to check the correct functionality of the instrument.

Self Test



This option is used to run a self test of the instrument to check the correct functionality of the instrument.

1. To activate, tap **Self Test** and then place the instrument on the white calibration tile.
2. Tap the **Start** icon in the display. The self test goes through 10 steps.

Measurement Option



This option is used to set auto measure mode.

Manual Measure: When set to Manual, you must press the Measure button or tap the screen once all three contact sensor indicators turn green in the display to take a measurement.

Automatic Measure: When set to Automatic, this option allows the instrument to automatically take a measurement once all three contact sensor indicators turn green in the display. No measurement switch press or screen tap is required. Once a measurement is taken, the instrument must be repositioned or the screen can be tapped for the next measurement.

Dark Mode Option



This option is used to help reduce measurement noise on very dark sample measurements.

Measurement times increase from 2.7 to 4.2 seconds when activated.

Off: When set to off, the option is not utilized.

Manual: When set to Manual, the instrument will display a message after the first measurement asking if you would like to turn on dark mode when a dark sample is detected. Select Yes to turn on Dark Mode or select No to continue without the option being used.

Automatic: When set to Automatic (default setting), the instrument automatically switches to dark mode after a dark sample is detected.

Speaker Option



This option is used to turn the instrument speaker on or off. The instrument beeps when the screen is tapped, after a measurement, and after a calibration. When set to on, the instrument beeps after a measurement and calibration.

WiFi Option




This option is used to turn WiFi on/off and setup the selected WiFi network.

Off: When set to off, WiFi is turned off (saving battery power). WiFi can still be activated by clicking the “WiFi Connect” icon on the Home screen.

On: When set to on, WiFi is turned on during normal operation and standby. WiFi is turned off during deep sleep mode.

WiFi Setup: Tapping the button will cause the instrument to scan for available network. After scanning the available networks are displayed on the screen. Tap a desired network and setup the password if required. When finished, tap OK to select the WiFi network.

Reset WiFi: Tapping this button clears the WiFi name, password and security.



Language



This option is used to set the language that is displayed on the instrument during operation. To set the language, tap **Language** and then tap the desired language.

N (measurement number) Option



This option is used to set the default number of measurements when using “Add new Job” option. The jobs created by the user software can define number of measurements individually for each job. Tap the option, enter the measurement number and tap the icon to save and exit.

Device Information



This option is used to view important instrument information such as hardware version, calibration reference serial number, battery data, etc.

Power Off



This option is used to power off the instrument. To access, tap **Power Off** and then tap **Power Off** to confirm.


Date and Time Option



This option is used to adjust the timestamp clock for the instrument.

1. To access, tap **Date and Time**. The flashing value in the field is the current value that can be adjusted.
2. Tap the “**Up**” arrow icon to increase the value.
3. Tap the “**Down**” arrow icon to decrease the value.

4. Tap the “**Left**” arrow icon to move the flashing field to the next field to the left.
5. Tap the “**Right**” arrow icon to move the flashing field to the next field to the right.
6. Tap the “**Checkmark**” in the center to save changes and exit the option.



Set LCD Color Option



This option is used to change the background color of the LCD screen slightly.

1. To access, tap **Set LCD Color**.
2. Tap the desired backlight color panel on the screen to save and exit the option.

Factory Reset Option



This option is used to reset the instrument to its factory default settings. All stored samples and calibration data will also be lost with the factory reset.

Calibration on the clean calibration reference supplied with the instrument needs to be performed after the reset.

Select **Yes** to reset to the factory default settings or select **No** to exit the setting without resetting. A factory reset will take approximately one minute to complete.


WiFi MODE

The WiFi icon is used to connect to the configured network once if WiFi is set to OFF in the Settings mode. The connection is terminated after exiting the WiFi Info/Connect screen.

The WiFi screen shows the status and detailed information about the WiFi network.

If WiFi is set to ON and a network is correctly configured in the settings menu, there is no option to set up the WiFi in this mode. The device always connects to WLAN as soon as available. This is indicated by the WiFi icon in the header bar which turns from greyed-out to white.

1. From the Home screen, tap the Connect icon (when WiFi is set to OFF in Settings) or the WiFi Info icon to access the WiFi screen.
2. The instrument will search for available networks. Available networks for connection appear with a green checkmark next to the name.



3. Tap the screen to open the Job Viewer screen.
4. Tap the Settings icon to view the WiFi Settings for the connected network.
5. Tap the Left (◀) arrow to return to the home screen.

CALIBRATION MODE

The instrument must be calibrated on the white tile every 14 days. Measurements with expired calibration are still possible, but with a warning at the beginning of each job.

Refer to the Cleaning section in the Appendices for information on cleaning the calibration reference.

NOTE: Make sure to use the calibration reference supplied with the instrument for calibrating. Do not substitute this reference with a reference from another instrument. The serial number on the reference should match the reference serial number displayed on the instrument calibration screen.

Calibration Notes

- Calibration should be performed at room temperature (best measurement performance when calibrated at 23°+/-1°C (73°+/-2°F) and 40-60% relative humidity).
- The **white tile in the calibration reference is severely affected by smudge marks, dust, and finger prints**. Refer to Appendices for calibration reference cleaning procedures.
- **Do not move instrument while taking a calibration measurement**. If motion is detected by the contact sensors, an error message will be displayed and calibration aborted.
- Make sure the USB cable is unplugged from the instrument before performing a calibration.

Calibration Reference


The calibration reference is designed to keep the white tile free of dust and debris.




Calibrating the Instrument

1. Select the **Calibration** option from the Settings menu as previously explained (see Entering Settings Mode). The message “Calibration expired” appears if the instrument needs to be calibrated. If calibration is not currently needed, the time remaining before the next calibration appears. To exit the calibration mode without calibrating, tap the Left (◀) arrow at the bottom of the screen.
2. Open the calibration reference and lay it flat. Position the instrument measurement port (1) over the white tile (2) by locating the two pins (3) in the calibration reference into the holes in the measurement base.

NOTE: The pins are keyed and will only insert in one direction.



- When ready, tap **Calibration** and then tap **Yes** to start calibration. Do not touch the instrument throughout the measurement sequence.



NOTE: If an error message appears after white calibration, try measuring the white tile again. If an error still occurs, clean the white calibration tile as explained in the Appendices. If the issue persists, perform Factory Reset in the Settings menu, turn the device off and on and repeat the calibration.

- After calibration is completed, remove the instrument from the calibration reference and close the reference case.

NOTE: It is recommended to perform a Self-Test after the Calibration Refer to the Settings screen.

JOB LIST MODE

The Job List mode is used to measure and delete sample data. The instrument stores measurements as jobs (multiple measurements per job). Each job must complete all required measurements before the next job can be selected. The measurement sequence is displayed at the top of the screen to help you track your progress for a job.

The following procedures explain the steps for measuring and deleting jobs. Refer to your software documentation for information on job uploading and downloading.

Measuring

In order for the instrument to obtain accurate and repeatable measurements, the bottom of the measurement port must be flat with the sample surface to be measured. Any movement of the instrument can cause the measurement angles to vary, greatly affecting measurements on metallic and pearlescent paint finishes. The contact sensors ensure the integrity of the measurement data.

IMPORTANT:

- To avoid discomfort, do not look directly into the measurement optics when the instrument is on and measuring.
- Do not move instrument while taking a sample measurement. If motion is detected by the contact sensors, an error message will be displayed and the measurement aborted.
- Measurement performance may decline under certain condensing conditions.
- Do not move the instrument on the sample surface with pressure. This may cause scratches to the sample surface.
- It is recommended to keep the sample around 23°C (73°F) as temperature could have influence on the color measurement.
- Downloaded jobs available for measurement do not have a green checkmark. Jobs that have a green checkmark have already been measured.



- Jobs in the list can be viewed in alphabetical order  or in unmeasured first order  by tapping the Job Sorting icon. To access the Job Sorting icon, press and hold the Up (▲) arrow icon for 2 seconds and release to advance to the top of the job list.

- The scroll bar on the right of the screen indicates the current position of jobs in the list.

1. From the **Home** screen, tap the Job List icon.
2. Select a downloaded job from the list or tap the **New Job** icon at the top of the screen to start a new job. After selection, the instrument goes into measure mode.



3. Locate the measurement port (1) in the bottom of the instrument over the measurement area while viewing the screen (2).
4. Gently rock the instrument until all three positioning indicators (3) in the screen turn green. This indicates that all three contact sensors (4) are activated.



5. Hold the instrument steady and press the Measure button or tap the screen to initiate a measurement in case the instrument is configured in Manual Mode. If the instrument is configured in Automatic Mode, the measurement will be triggered as soon as (with a one-second delay) the instrument is correctly positioned on the check zone and all pins are in contact (green indicators on UI). You can also initiate a measurement by tapping the screen in Automatic Mode if desired. Continue to hold the instrument steady until the progress bar in the screen reaches 100%.

NOTE: If an error occurs after the measurement, tap **OK** on the screen and try measuring again.

6. Continue with the remaining area measurements to complete the job.
7. After the last measurement is completed, the quality of the measurement is indicated with a 5 point system. Five points indicates excellent measurement without variation between the readings, 3-4 points indicates good measurement and 1-2 points indicates an acceptable measurement. After the final measurement is taken, the Save job data screen appears. Tap the screen to save the job and return to the Job List screen.



8. If the job was created on the instrument using the New Job feature, you can edit the name if desired. Tap on the Edit icon at the bottom of the screen and enter a job name using the virtual keyboard. Tap the Enter icon to save the job name.



Deleting Jobs

Single Job

1. To delete a single job or job data, tap the job from the Job list. You will need to tap the Down (▼) or Up (▲) arrow icons if the job you want to delete is not showing up in the list. You can quickly get to the end of

the job list or top of the job list by pressing and holding the Down (▼) or Up (▲) arrow icon for 2 seconds and then releasing.




2. Tap **Delete Data** or **Delete Job** in the screen to continue. If Delete Data is selected, only the data will be deleted and not the job.
3. A message appears asking you to confirm that you want to delete the data or job. Tap **Yes** to confirm or **No** to return to the Job List screen.



All Jobs

1. To delete all jobs, press and hold the Down (▼) arrow icon for 2 seconds and release to advance to the end of the job list.
2. Tap the delete all jobs icon  at the bottom of the screen.



3. A message appears asking you to confirm that you want to delete the job. Tap **Yes** to confirm or **No** to return to the Job List screen.



APPENDICES

Service Information

X-Rite provides repair service to their customers. Because of the complexity of the circuitry, all warranty and non warranty repairs should be referred to an authorized service center. For non warranty repairs, the customer shall pay shipping and repair cost to the authorized service center, and the instrument shall be submitted in the original carton, as a complete unaltered unit, along with all the supplied accessories.

X-Rite, Incorporated has offices around the world. You can contact us using one of the following methods:

- To identify the X-Rite service center nearest you, please visit our web site at www.xrite.com.
- For online help, visit our web site and click the **Support** link.
- Send an e-mail to Technical Support (casupport@xrite.com) detailing your problem and listing your contact information.

Cleaning the Instrument

The exterior of the instrument may be wiped clean with a cloth dampened in water or mild cleaner.



Important Notes:

- DO NOT use any solvents to clean the instrument, this will cause damage to the cover and internal electronic components.
- Compressed air should not be used to clean the instrument. Cleaning the instrument with blown air can cause dirt on the outside of the instrument to enter into the device, and contaminate optical components.

Cleaning the Calibration Reference

The white tile in the calibration reference should be cleaned using a mild soap and warm water solution, thoroughly rinsed with warm water, and wiped dry with a clean, lint-free cloth. You must let the reference dry completely before taking a calibration measurement.

Replacing the Battery Pack



Use on Li-ion battery pack provided by X-Rite (P/N TPZ-27313); other types may burst causing personal injury.

IMPORTANT: Before replacing the Li-ion battery pack, make sure that the device is in a clean environment and on a flat, and non-slippery surface.

WARNING: Any accidental damage done to internal parts of the device (optics, mechanics, electronics) will void the warranty of the device.

NOTE: Time and date are lost when the battery is disconnected. It is not possible to set the clock in the Setting menu.


Connect the instrument to the PC and use the utility software or the application software to set time and date.

This information is used for identification of the measurements.


1. Carefully position the instrument on the left side and remove the 2 screws in the base plate using a 2 mm allen key). Compress the cover slightly if the screws do not fall out.




2. Lift up on the right side panel and remove.



3. Press downward on the clip at the top of the battery connector. Slowly pull battery connector outward and remove the old battery pack.



4. Insert the new battery pack into the clip and plug in the battery connector.



5. Reattach the side panel and insert the long screw in the back hole and the short screw in the front hole. Carefully tighten the 2 screws in the base plate with very little torque.



Troubleshooting

Prior to contacting X-Rite support department for instrument problems, try the applicable solution(s) described below. If the condition persists, contact us using one of the methods listed in the Service Information section.

Problem	Cause	Solution
Instrument screen remains dark.	Instrument is turned off.	Turn instrument on by pressing the power/measure button.
	Instrument is in power down mode.	Touch the screen or lift the instrument.
	Battery is very low.	Charge the battery min. 1 hour. After max. 5 minutes the screen will turn on.
	Battery is defective.	Charge the battery. If the screen does not turn on after max. 5 minutes check if the USB cable is correctly connected to the computer or power supply (USB ports on computer monitors and keyboards do not deliver enough power). If it still does not work the battery needs to be replaced.
Screen is instable (turns on and off periodically) when the instrument is connected to a computer or power supply.	Battery is defective.	Battery needs to be replaced.
Screen is frozen.	Firmware is locked up.	Disconnect USB cable. Press and hold the power/measure button for 10 seconds and then release. Instrument turns off. Instrument can be started normally.
Measurement error or results appear inaccurate.	Material being measured is damaged (e.g. scratched).	Repeat measurement.
	Calibration was performed on a dirty calibration reference.	Clean the calibration reference and repeat the calibration per procedure in the Calibration section.
	Instrument requires calibration.	Perform calibration on calibration reference followed by a self test. If calibration and self test fails, the instrument is defective. Contact technical support.
	Instrument is defective.	Perform a self test in the Settings menu. If the self test fails the instrument is defective. Contact technical support.
Calibration procedure fails.	Instrument movement, dirty calibration tile, etc.	Try measuring the white tile again. If an error still occurs, clean the white calibration tile as explained in the Appendices. If the issue persists, check battery status (Device Information in Settings menu), perform a Factory Reset in the Settings menu, turn the device off and on, and repeat the calibration.
	Instrument defective.	Contact technical support.
Instrument and software not communicating (USB connection).	USB cable not connected.	Connect the USB cable between the computer and the instrument.
	USB cable is defective.	Exchange USB cable.

	Communication crashed between application software and the instrument.	Unplug the USB cable, wait 1 second and connect the cable again. If the communication still does not work, close and restart the software application. Restart the instrument. If the communication still does not work, reboot the computer.
Instrument will not measure or calibrate.	Contact sensor(s) do not properly contact the sample surface.	Lift the instrument and place it properly on the sample. Make sure that all 3 sensor indicators on the screen turn green.
	Contact sensor(s) are not working correctly. Sensors may be stuck due to dirt or paint; or they are defective.	Open a new job to show the 3 sensor indicators on the screen and place the instrument on a flat surface and then lift it. If one or more of the sensor indicators in the screen do not change color when lifted, there may be a problem with the contact sensor(s). Contact technical support.
	Sensor indicators in the display do not change color.	Contact sensors are not working correctly. Put the instrument into measure mode and place the instrument on a flat surface and then lift. If one or more of the sensor indicators in the display do not change color when lifted, there may be a problem with the contact sensor. Contact technical support.
WiFi not connected.	WiFi turned off.	Turn on WiFi in Settings menu or tap "Connect" in home screen to connect once.
	WiFi signal too weak or not available.	Approach the WiFi access point; optimally closer than 5 meters.
WiFi not connecting.	Network not correctly set.	Perform the WiFi setup procedure in WiFi Option, located in the Settings menu by scanning the available networks. Select the desired network and enter the password.
WiFi network cannot be configured.	Wrong password entered.	Repeat the WiFi setup procedure in WiFi Option, located in the Settings menu by scanning the available networks, selecting the desired network and enter the password. Make sure the password is entered correctly. This can be checked by switching the password entry to human readable (eye symbol above password entry).
	WiFi signal too weak.	Approach the WiFi access point; optimally closer than 5 meters. Repeat the WiFi setup procedure in WiFi Option, located in the Settings menu by scanning the available networks. Select the desired network and enter the password.
Shutter error.	Instrument defective.	Contact technical support.
Multiple error messages.	Instrument encountered a cascade of errors.	Press OK button in error message for 2 seconds.
Date and time wrong.	Incorrect setting.	Refer to instruction in manual.

Instrument Specifications**Environmental**

Operating Temp:	50°F to 95°F (10°C to 35°C)
Humidity Max:	85% RH max (non condensing)
Storage Temp:	-4°F to 122°F (-20°C to 50°C)

Battery

Type:	Lithium Ion Battery
Cell Size:	18650
Nominal Voltage:	3.6V
Capacity:	2.15 Ah
Max. discharge current:	4A
Max. charge current:	2.15A
Inner resistance:	<= 120 mΩ
Compliance:	UN38.3, IEC62133B, CE
Protection:	over current, over charge, over discharge



Corporate Headquarters

X-Rite, Incorporated
4300 44th Street SE
Grand Rapids, Michigan 49512
Phone 1 800 248 9748 or 1 616 803 2100
Fax 1 800 292 4437 or 1 616 803 2705

European Headquarters

X-Rite Europe GmbH
Althardstrasse 70
8105 Regensdorf
Switzerland
Phone (+41) 44 842 24 00
Fax (+41) 44 842 22 22

Asia Pacific Headquarters

X-Rite Asia Pacific Limited
Suite 2801, 28th Floor, AXA Tower
Landmark East, 100 How Ming Street
Kwun Tong, Kowloon, Hong Kong
Phone (852)2568-6283
Fax (852)2885 8610

Please visit www.xrite.com for a local office near you.